

Project Name	Released By	SW Build Numbers	Release From Test Date
CORIOmatrix	David Reynaga	M302F28 (Firmware) 1.0.0.1137 (Web UI)	22/07/2014
Release Description			
Firmware update (including Web UI) Formal release - some known issues below			
Previous Release			
M302F24 (Firmware)	1.0.0.812 (Web UI)	02/07/2014	
New Features Included In Release			
Web UI - Browser based User Interface Presets - The ability to save and load up to 50 routing configurations			
Defects Resolved With This Release			
Audio issues (800751, 800796, 800821, 800831, 800854, 800855, 800861, 800866) Routing issues (800852, 800857, 800859, 800862) Preset issues (800824, 800849, 800864) User interface issues (800847, 800850, 800856, 800858, 800865) Monitor issues (800846)			
Known Issues With This Release			
Disappearing Output audio bars on Monitor output (799546) AFV Choice' Alias is not retained when selected (799562)			
Supported Web Browsers			
Firefox (version 28 or later) Chrome (version 34 or later) Internet Explorer (version 10 or later) Safari (version 6 or later)			
Installation Instructions			
Please backup your current settings to the internal SD Card. IF YOU DO NOT save your settings all settings will be LOST - therefore create a backup of your settings prior to release.			
Points of contact			
Product Manager Tony McAhren Tony.McAhren@tvone.com		R&D Paul Hounslow paul.hounslow@tvone.com	

Project Name	Released By	SW Build Numbers	Release From Test Date
CORIOmatrix	David Reynaga	M302F28 (Firmware) 1.0.0.1137 (Web UI)	22/07/2014
Defects Resolved With This Release Details			
<p>Configuring Audio routing should only show Channel A for Audio Card io's (800751)</p> <p>Audio Routing Not Saving In Presets (800796)</p> <p>Output 1 and 2 will not route audio on take (800821)</p> <p>AFV audio status lozenge (yellow) not saved in preset (800824)</p> <p>Audio Follow video option on AES card io route (800831)</p> <p>Monitor tab not reflecting actual pre-saved monitor configuration (800846)</p> <p>Unable to change source loss colour (800847)</p> <p>Basic user is able to delete presets (800849)</p> <p>Web UI not reflecting DHCP settings (800850)</p> <p>Unable to route brakeaway audio (800852)</p> <p>Audio breakaway fails (800854)</p> <p>Audio on every A2-7322 output (800855)</p> <p>Revert button does not do anything and the message is not meaningful (800856)</p> <p>After revert or switch to immediate mode the routing table does not reset correctly (800857)</p> <p>Routing table cells briefly flash blue when selecting an Audio Card in immediate mode (800858)</p> <p>Able to perform illegal audio routing on breakaway output. (800859)</p> <p>AFV not working in immediate mode (800861)</p> <p>Routing AES input channels to HDMI outputs requires output channels to be populated (800862)</p> <p>AES card routing not saved in presets (800864)</p> <p>Spelling/grammar errors in UI (800865)</p> <p>Audio card/table still displays after unchecked (800866)</p>			
Points of contact			
Product Manager Tony McAhren Tony.McAhren@tvone.com		R&D Paul Hounslow paul.hounslow@tvone.com	