

CORIOview™ Firmware M405_66B

Released by: Neil Baptiste

This software is for:

- Hardware: CORIOview [NEW]
 - Firmware: use CORIODiscover v1.5.2.2 or above to update to this version
 - Software: CORIOgrapher v2.6.3.1
- ✔ For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest software here:

CORIOgrapher: tvone.crmdesk.com/answer.aspx?aid=20766

CORIODiscover: tvone.crmdesk.com/answer.aspx?aid=21697

Previous releases

- None

Contact us

www.tvone.com

tvONE NCSA
North, Central and South America

✉ Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA
Europe, Middle East, Africa and Asia Pacific

✉ Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com

CORIOview™ firmware M405_66B

Released by: Neil Baptiste

New

- New Product Launch

Fixed

- None

Notes

- Known issues:
 - In certain rare situations, it may be possible to get a label to display a corrupted image. However, the system will recover itself in a maximum of 40 seconds (if you have a 8 Input set up) and less for 4 input models.

Workaround: just un-select the alias or Info label from the front panel or CORIOgrapher and immediately re-select it to re-write the label.
 - Cloned 2nd Outputs are not yet supported on this device, only the 1st output will be active when using a 2xOutput card type. Feature will be enabled at subsequent release.