

# CORIOview™ Firmware M409\_06 (Dynamic Mode)

Released by: Neil Baptiste 17<sup>th</sup> Feb 2020

#### This software is for:

Hardware: CORIOview

• Firmware: use CORIOdiscover v1.7.2.2 or above to update to this version

Software: CORIOgrapher v2.9.3.3

For help with connecting, setting up, and using CORIOgrapher, see CORIOgrapher Help, or the Quick Start Guide that came in the box.

### Downloads

Download the latest firmware here: tvone.com/firmware-updates

Download the latest software here:

CORIOgrapher:

http://tvone.com/tech-support/software/183-coriographer-software

CORIOdiscover:

http://tvone.com/tech-support/software/185-coriodiscover-software-download

### Previous Releases

M407\_06

#### Contact us

www.tvone.com

tvONE NCSA North, Central and South America

Sales: sales@tvone.com
Support: tech.usa@tvone.com

tvONE EMEA

Europe, Middle East, Africa and Asia Pacific

Sales: sales.europe@tvone.com
Support: tech.europe@tvone.com







# CORIOview™ Firmware M409\_06 (Dynamic Mode)

Released by: Neil Baptiste 17<sup>th</sup> February 2020

### [New Features]

- Dynamic Mode.
- Labelling on Media/IP Streams
- Low Latency IP Streams

### Fixed

- REST API values do not update until CLI read.
- If you apply any crop to an input and you have a label turned on, and then you then unplug or the source to that input is turned off. The label will disappear and will not return until that input sees a valid source again. So, when source loss colour is shown you will have no labels.

#### Notes

- Known Issues: To be addresses in the next release
  - If the unit is reset or power-cycled, the next time you log in with CORIOgrapher, you will be asked to select dynamic or classic mode
  - Saving the configuration via CORIOgrapher does not include the play-onstartup parameter.
  - Labels display incorrectly the first time after rebooting the unit into secure communications mode
  - Audio can stutter when moving between certain media clips using the Streaming Media Input module.
  - o Front Panel will unlock using either button 1 or 2
  - o After a restoreAll API command, labels are slow to refresh.