

Project Name	Released By	SW Build Numbers	Release Date
C2-8000	Richard Mallett	499	26th March 2014
ease Description			
This release encompa	sses a number of bug fixes ar	nd reliability improvements.	
elease Type			
Full Release	1 1 4	_	
elease Notes valid from	release date:	4	
26th March 2014	Delege		
ew Features Included In			
hanges since version 438		Lawara	
•	unication resilience to externa d HDMI detection on DVI-U οι		
•	o receive 480i & 576i resolutio	•	
•	faster - also includes updated		
•	DVI-U output when HDMI re	•	
Added CEA ID code to	DVI-0 output when holvinte:	Solutions used.	
efects Resolved With Th	nis Release		
hanges since version 438	:		
Corrected some HD re	esolution timings		
Fixed issue in Multi-PI	P mode where Output 2 may	become unstable.	
Corrected issue where	e 480i & 576i resolution would	not be sent over DVI-U to HDMI disp	play.
Fixed hanging-line for	1080i input from SDI source.		
Improved SIS reliabilit	-		
Fixed keying issue wh	ere 'Max' value was out by 1.		
Improved reliability of	DVI-U inputs.		
nown Issues With This I	Release		
Loading a deleted pre-	set may cause unpredictable i	results.	
The CC-300 is not sup	pported with this release.		
nstallation Instructions			
lownload and run the exec	cutable file. This will install to	C:\Program Files\CORIO2.	

Run the firmware upgrader. Connect an RS232 cable from your PC to the unit.

Select the correct COM port on the software and click Update.

## Points of contact

Product Manager R&D

Product Manager Technical
Tony McAhren David Reynaga

david.reynaga@tvone.com